



SECRET/CONTROL - U.S. OFFICIALS ONLY

25X1

- 2 -

8. Damage to the RUS

[redacted] a member of the Russian Supervisory Commission mentioned at a routine conference that the Russian vessel RUS had recently suffered damage in Far Eastern waters, occasioned by a "hit" of an unspecified nature. The net result of this mishap was that the components of the main engines shifted on their foundations. Because of this, instructions have now been given that the engine components of all other Russian vessels under repair are to be more firmly secured to their foundations.

25X1

[redacted] 25X1

SECRET/CONTROL - U.S. OFFICIALS ONLY